Ser. No.: 10/781,129 Lance T. Hampel Page 2 of 7

Specification Amendment:

Please amend paragraph 48 of the specification as follows:

-- [0048] At each location where a hole 24 is formed, there are lines 26 (e.g., small grooves) molded into the sides of the deck 18 and on the top surface of the runners 13 to show where to put the threaded fasteners for mounting the cabin panels, i.e. for mounting the cabin front, sides, and rear. The structural foam material of the deck 18 is thicker in these locations, a result of the placement of the bosses 28 that contain the holes 24 that provide the fastening points for the runner wear plates 20. Referring to Fig. 8 and Figs. 17-20, the generally cylindrical boss 28 in which the hole 24 is formed, extends all the way to the underside of the top of the deck so as to substantially fill the void on the inside of side wall 30 at the location of line 26. Thereby, a self threading fastener 16 can be driven into the side wall 30 at the line 26 and be substantially fully engaged to a depth significantly greater than the thickness of the sidewall 30 by the material of the [[deck]] base 12, i.e., to a depth approximately equal to the lateral dimension of the boss 28. Triangular reinforcing structures provided by ribs 29 (Fig. 9) provide additional reinforcement by tying the bosses 28 into the inner sidewall 31, and provide additional thickness where the ribs 29 intersect the boss 28 for the fasteners 16 to penetrate.--